

Grand Rapids Water Resource Receovery Facility  
Former Incinerator Ash Lagoon  
August 17, 2021  
Regulated PFAS Sampling Results

- Non-Detect
- Detection
- Exceedance
- ⊕ Groundwater Monitoring Points
- ⊕ Shallow Aquifer Sample
- Deep Aquifer Sample
- 8-17-2021 Groundwater Contours
- ➡ Approximate Groundwater Flow Direction
- ▭ Former Incinerator Ash Lagoon

Dewatering Wells  
Gallons Per Minute

- 0
- 1 - 10
- 11 - 25
- 26 - 50

Grand River

Market Ave. SW

